

Submerged Arc Welding Table Operator



Reports To

Plate Production Coordinator or Plate Shift Supervisor

Summary

The Stationary Machine Operator is required to ensure the safe, efficient operation, cleaning of and running adjustments for their machine(s). Responsible for the maintenance of prescribed quantity and quality of product produced. Other responsibilities include troubleshooting machine basic performance, making adjustments and calling for additional resources as required.

Job Duties

- Maintain high production numbers for daily goals
- Produce product with an emphasis on quality
- Operate overlay machinery and make running adjustments as required
- Follow running instructions
- Provide feedback and maintenance requests to improve machine performance
- Complete all assigned Quality checks
- Participate in training and cross training, improvement initiatives including health and safety and quality improvement
- Safely operate lifting equipment (forklift, crane).
- Adhere to all workplace safety and quality policies, procedures and processes.
- Use all required safety equipment, e.g. Steel-toed safety boots, safety glasses / goggles, etc.
- Optimize productivity by reducing downtime.
- May perform other duties as assigned by supervisor.
- Maintain clean and safe work area.
- Learn and follow Trimay's QMS (quality management system).
- Propose continuous improvement and complete training as per QMS system.
- Detailed work instructions and responsibilities as per job package
- Performs other duties as required

Requirements

- High School diploma, GED or equivalent
- Experience as a stationary machine operator preferred
- Highly punctual
- Reliable means of transportation
- Able to work as a functioning member of a team
- Strong work ethic
- Ability to work independently in a busy environment
- Experience with routine maintenance operations
- Highly flexible, with solid interpersonal skills that allow one to work effectively in a diverse working environment
- Able to effectively communicate both verbally and in writing

- Able to work well under pressure
- Strong attention to detail
- Able to deal with people sensitively, tactfully, diplomatically, and professionally at all times
- Willingness to cross train to other equipment/company divisions.

Work Conditions

- Physical ability to lift up to 50lb
- Safety equipment may be required, e.g. steel-toed safety boots, safety glasses/goggles, etc.
- Overtime as required
- Hazards associated with the trade

Apply Now at:

Email

Attention: **Evelyne Broere** Controller

ebroere@trimay.ca

Mail or drop off at reception:

Trimay Wear Plate LTD
4805 – 82 Ave. NW,
Edmonton, AB, Canada
T6B 0E5